


# CARBURETOR TUNING CHART

By ANDREW BROWN

Use this worksheet to determine your perfect tuning. The metrics labelled are good standards, and columns on the right are for anything extra you want to track.

Idle	Slide	Needle Type	Needle Clip	Main Jet	Top Speed	Tach	Notes										
45	50	W7	2 <sup>nd</sup>	99	26	7600	Cuts out after ½ throttle										



Even more tuning metrics: type or using an air box/filter, atomizer, idle screw turns, temp, float weight, rich/lean at specific throttle positions  
 Wizard level tuning metrics: Timing, clutch engage tach, plug chop color, var. weights, Spring color, gearing, cylinder compression  
 Elites only: Foot stance, color helmet, piston seize tally